

## Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>


2016/01/14

The engine company.



# Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>



## Login

Language  
English

Username  
Cxxxxx

Password  
\*\*\*\*\*

Login Register

[Forgot Username or Password](#)

## News

08-05-2014  
[Noticias Deutz Spain](#)  
09-05-2014  
[Noticias Deutz AG](#)

## Tips

The Infor Supplier Exchange online help contains step-by-step instruction and explanations of Infor Supplier Exchange components. To access the help, click "?" on the application's navigation bar.



## Links

[www.infor.com](http://www.infor.com)  
[Manual Deutz Spain, S.A.](#)

- 1.- Select language.
- 2.- User: **Cxxxxx** (C=Quality y xxxxx = Supplier Nr.)
- 3.- Password: **Cxxxxx**

# Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>




- 3 Unviewed Purchase Orders
- 1 DMN requiring Containment Response
- 1 DMN requiring Corrective Response


A DMN is a quality complaint

# Supply Web – Defective Material Notifications (DMN)


<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>



← → ↻ [suppliers.deutzspain.com:8019/supplyWeb/account/completeLogin](http://suppliers.deutzspain.com:8019/supplyWeb/account/completeLogin) 🔍 ⌵ ⌵ ⌵


 Infor Supplier Exchange® 11.4.6.024. Proveedor 99995 ↗

Demand ▾ Shipments ▾ Receipts ▾ Defective Materials ▾ Delivery Performance ▾ Parts Per Million ▾ Supplier Performance ▾ Document Management ▾ More... ▾

◀ ⏪ | 🖨️ 📄 📁 | ? | Deutz Spain ▾ 

[Event Management Console](#) Defective Material Notice




**DMN requiring Containment Response** 1 Total | 08.02.2016


View	Defective Material Notice ID	Facility	Ship To	Ship From	Part	Effective Date
	75	DEUTZ SPAIN ZAFRA	DEUTZ-ALM		99996666	08.02.2016

**Click on the "glasses" for details**


# Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>

← → ↻    

 Infor Supplier Exchange® 11.4.6.024. Proveedor 99995 ↗

Demand ▾ Shipments ▾ Receipts ▾ Defective Materials ▾ Delivery Performance ▾ Parts Per Million ▾ Supplier Performance ▾ Document Management ▾ More... ▾

◀ ⏪ ⏩ ▶  

### Defective Materials DMN Edit

Facility	Ship To	Supplier
DEUTZ SPAIN ZAFRA Crtá.Badajoz -Granada, Km 74,6 06300 ZAFRA (Badajoz) SPAIN	DEUTZ-ALM Calle Guadiana 38-40 Pol. Ind. Los Caños 06300 Zafra (Badajoz) SPAIN	Proveedor Test 99995 Pg Gracia 56 08007 Barcelona SPAIN

Part

Part Number: 99996666  
Part Description: ART. TES PARA S.E. PEDIDO CERRADO

Header Information	Problem Description	Disposition	Supplier Information	Action Information	Claims	DMN History
DMN ID: 95 Reject Tag Number: 123456 Receipt Number: 123456 Receipt Date: 07.02.2016 Sample Quantity: 1,000 Rejected By: G. Gahete (DS-QL) Reason Code:Description: FM	Falta de material/Lack of material					PO Number: 987654 Warning Only: No Received Quantity: 1,000 Rejected Quantity: 5 Quantity Non-Conforming: 10 Rejected Date: 07.02.2016 Source of Defect:Description: CR Control recepción/Incoming goods inspection


[Update](#) [Cancel](#)

In "Problem Description" is where we put the basic information about the complaint.

For details, photographs, ...we have attached an EXCEL file, similar to ARC file we have sent till now

# Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>



The screenshot shows the 'Defective Materials DMN Edit' page in the Infor Supplier Exchange. The page is divided into several sections: Facility, Ship To, Supplier, Part, and a navigation bar. The 'Action Information' tab is selected and circled in blue. Below this tab, the 'Containment' section is visible, containing fields for 'Response Required', 'Response Due Date', 'Containment Plan', 'Containment Date', 'Containment Status', and 'Customer Feedback'. Annotations with blue boxes and arrows point to these fields, providing instructions: 'Briefly describe the actions of the containment plan.' points to the 'Containment Plan' field; 'In 'Action Information' you must define the containment and corrective actions.' points to the 'Action Information' tab; and 'Containment actions implementation date' points to the 'Containment Date' field. At the bottom of the page, there are 'Update' and 'Cancel' buttons.

Facility: DEUTZ SPAIN ZAFRA, Crta.Badajoz -Granada, Km 74,6, 06300 ZAFRA (Badajoz), SPAIN

Ship To: DEUTZ-ALM, Calle Guadiana 38-40, Pol. Ind. Los Caños, 06300 Zafra (Badajoz), SPAIN

Supplier: Proveedor Test 99995, Pg Gracia 56, 08007 Barcelona, SPAIN

Part: Part Number: 99996666, Part Description: ART. TES PARA S.E. PEDIDO CERRADO

Header Information | Problem Description | Disposition | Supplier Information | **Action Information** | Claims | DMN History

Containment

Response Required: Yes  
Response Due Date: 09.02.2016

**Containment Plan**

Briefly describe the actions of the containment plan.

In 'Action Information' you must define the containment and corrective actions.

Containment Date:

Containment Status: None

Customer Feedback:


Containment actions implementation date

Update Cancel


# Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>

← → ↻  🔍 ⭐ ☰

 Infor Supplier Exchange® 11.4.6.024. Proveedor 99995 ↗

Demand ▾ Shipments ▾ Receipts ▾ Defective Materials ▾ Delivery Performance ▾ Parts Per Million ▾ Supplier Performance ▾ Document Management ▾ More... ▾

◀ ⏪ ⏩ ▶ |  

## Defective Materials DMN Edit

Facility	Ship To	Supplier
DEUTZ SPAIN ZAFRA Ctra.Badajoz -Granada, Km 74,6 06300 ZAFRA (Badajoz) SPAIN	DEUTZ-ALM Calle Guadiana 38-40 Pol. Ind. Los Caños 06300 Zafra (Badajoz) SPAIN	Proveedor Test 99995 Pg Gracia 56 08007 Barcelona SPAIN

Part

Part Number: 99996666  
Part Description: ART. TES PARA S.E. PEDIDO CERRADO

Header Information   Problem Description   Disposition   Supplier Information   **Action Information**   Claims   DMN History

### Corrective Action

Response Required: Yes  
Response Due Date: 12.02.2016

Corrective Plan:

Briefly describe the corrective actions

Corrective Date:

Corrective Status: None

First Corrected Shipment Date:

Customer Feedback:

Corrective actions  
implementation date

# Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>

suppliers.deutzspain.com:8019/supplyWeb/account/completeLogin

Infor Supplier Exchange® 11.4.6.024. Proveedor 99995

Demand Shipment Receipts Defective Materials Delivery Performance Parts Per Million Supplier Performance Document Management More...

Deutz Spain

## Defective Materials DMN Edit

Facility	Ship To	Supplier
DEUTZ SPAIN ZAFRA Ctra.Badajoz -Granada, Km 74,6 06300 ZAFRA (Badajoz) SPAIN	DEUTZ-ALM Calle Guadiana 38-40 Pol. Ind. Los Caños 06300 Zafra (Badajoz) SPAIN	Proveedor Test 99995 Pg Gracia 56 08007 Barcelona SPAIN

Part

Part Number: 99996666  
Part Description: ART. TES PARA S.E. PEDIDO CERRADO

Header Information Problem Description Disposition Supplier Information **Action Information** Claims DMN History

Empty form area for DMN details.

Corrective Date:   
Corrective Status: None  
First Corrected Shipment Date:   
Customer Feedback:

To save the changes, click "UPDATE"

To inform about your action details we use an 8D format attached (as template) that you must fulfill

Customer Template:  
**Formato 8D\_DS.xls 26.01.201x**

Supplier Attached Files:  Ningún archivo seleccionado



# Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>

Browser address bar: suppliers.deutzspain.com:8019/supplyWeb/account/completeLogin#

infor Infor Supplier Exchange® 11.4.6.024. Proveedor 99995

- Demand
- Shipments
- Receipts
- Defective Materials
- Delivery Performance
- Parts Per Million
- Supplier Performance
- Document Management
- More...

Navigation bar with icons: Home, Print (circled in blue), Refresh, Help, Search (Deutz Spain), and DEUTZ logo.

[Defective Materials](#) View DMN

Facility	Ship To	Supplier
DEUTZ SPAIN ZAFRA Crtá.Badajoz -Granada, Km 74,6 06300 ZAFRA (Badajoz) SPAIN	DEUTZ-ALM Calle Guadiana 38-40 Pol. Ind. Los Caños 06300 Zafra (Badajoz) SPAIN	Proveedor Test 99995 Pg Gracia 56 08007 Barcelona SPAIN

To print DMN

Part

Part Number: 99996666  
Part Description: ART. TES PARA S.E. PEDIDO CERRADO

Header Information Problem Description Disposition Supplier Information Action Information Claims DMN History

DMN ID: 95	PO Number: 987654
Reject Tag Number: 123456	Warning Only: No
Receipt Number: 123456	Received Quantity: 1000.0
Receipt Date: 07.02.2016	Rejected Quantity: 5.0
Sample Quantity: 1000.0	Quantity Non-Conforming: 10.0
Rejected By: G. Gahete (DS-QL)	Rejected Date: 07.02.2016
Reason Code:Description: FM	Source of Defect:Description: CR
Falta de material/Lack of material	Control recepción/Incoming goods inspection

# Supply Web – Defective Material Notifications (DMN)

<http://suppliers.deutzspain.com:8019/supplyWeb/account/login>

← → ↻ suppliers.deutzspain.com:8019/supplyWeb/account/completeLogin#
🔍 ☆ ☰

**Imprimir**  
Total: **1 página**

**Guardar** Cancelar

---

Destino Guardar como PDF

Cambiar...

---

Páginas ● Todo

○ p. ej. 1-5, 8, 11-13

---

Diseño Vertical ▼

---

Tamaño del papel A4 ▼

---

Márgenes Predeterminado ▼

---

Configuración

Simplificar página

Encabezado y pie de página

Gráficos de fondo

22/03/2016 Infor Supplier Exchange® 11.4.6.024 | Supplier | Admin

Facility	Ship To	Supplier
DEUTZ SPAIN ZAFRA Crtá.Badajoz -Granada, Km 74.6 06300 ZAFRA (Badajoz) SPAIN	DEUTZ-ALM Calle Guadiana 38-40 Pol. Ind. Los Caños 06300 Zafra (Badajoz) SPAIN	Proveedor Test 99995 Pg Gracia 56 08007 Barcelona SPAIN

---

Part

Part Number: 99996666  
Part Description: ART. TES PARA S.E. PEDIDO CERRADO

---

Header Information	Problem Description	Disposition	Supplier Information	Action Information	Claims
95	DMN ID:		987654	PO Number:	
	Reject Tag Number:		No	Warning Only:	
123456	Receipt Number:		1000.0	Received Quantity:	
123456	Receipt Date:		5.0	Rejected Quantity:	
07.02.2016	Sample Quantity:		10.0	Quantity Non-Conforming:	
1000.0	Rejected By:		07.02.2016	Rejected Date:	
	G. Gahete (DS-QL)			Source of Defect:Description:	
	Reason Code:Description:			CR	
	FM				
	Falta de material/Lack of material			Control recepción/Incoming goods inspection	

<http://suppliers.deutzspain.com:8019/supplyWeb/account/completeLogin#>
1/1